405 MOTORS

24115 SNOHOMISH WOODINVILLE RD
WOODINVILLE, WA 98072
Phone: 425-486-4240 Fax: 425- -

07/15/2017 4:06:11 PM
ESTIMATE #
3835

405 MOTORS
SALES DEPARTMENT
6430 240TH ST SE
WOODINVILLE, WA 98072
Cell 425-949-4550

2009 Acura TL SH-AWD Silver
Odometer In: 86926
License: 005757
Unit # 005757
VIN: 19UUA96559A005757
Eng: 3.7L, V6 (224CI) VIN(9)

Estimate

Perform Multipoint Inspection
Brakes: FR 35% RR 10%

Oil Service: Engine Oil SAE 5W30 Synthetic Blend w/ Filter

This vehicle has been checked for the following components :

1. Fluids, Belts, Wipers, Bulbs, Tires, Wheels, Alignment, Basic Power Options .
2. Charging System - Battery, Alternator, Terminals and relevant electrical wiring .
3. Engine - Idle, Leaks, Hoses, Valves, Clamps and overall visual condition .
4. Transmission, Clutch, CV joints & axles, Transfer case, Drive axle, Drive shaft and U -joints.
5. Suspension -Struts & Shocks, Bushings, Links and spring assembly .
6. Water pump, Radiator & acc . Fan, Thermostat and applicable cooling system hoses & Tubes .
7. AC Compressor, AC Clutch, Blower motor, AC Lines and Heating.
8. Exhaust System – Muffler, Exhaust & Y-Pipe, Resonator and applicable clamps & holders .
9. Drivability – pre-inspection test drive and post -service drivability test drive .

Please note that additional services may be required as part of the regular maintenance .

Notes & Recommended items :

Labor: $0.00 **Parts:** $0.00 **Job Total:** $120.00

Engine Oil SAE 5W30 Synthetic Blend
Lube, Oil & Filter

Labor: $39.95 **Parts:** $0.00 **Job Total:** $39.95

Front brake service

Part Number	Description	Quantity	Sale	Extended
1102-03	Brake Pad Set-Front - with Shims	1.00	$42.82	$42.82
45251-TK4-A00	Brake Disc-Front	2.00	$79.20	$158.40

Labor: $80.00 **Parts:** $201.22 **Job Total:** $281.22

Rear brake service

Part Number	Description	Quantity	Sale	Extended
1103-03	Brake Pad Set-Rear - With Shims	1.00	$39.52	$39.52

Labor: $80.00 **Parts:** $39.52 **Job Total:** $119.52

Hood struts

Part Number	Description	Quantity	Sale	Extended
O2020-613406	Hood Strut-Left	1.00	$22.47	$22.47
O2020-613406	Hood Strut-Right	1.00	$22.47	$22.47

Labor: $20.00 **Parts:** $44.94 **Job Total:** $64.94

405 MOTORS

24115 SNOHOMISH WOODINVILLE RD
WOODINVILLE, WA 98072
Phone: 425-486-4240 Fax: 425- -

07/15/2017 4:06:11 PM
ESTIMATE #
3835

405 MOTORS
SALES DEPARTMENT
6430 240TH ST SE
WOODINVILLE, WA 98072
Cell 425-949-4550

2009 Acura TL SH-AWD Silver
Odometer In: 86926
License: 005757
Unit # 005757
VIN: 19UUA96559A005757
Eng: 3.7L, V6 (224CI) VIN(9)

Estimate

Continued From Previous Page

Front Rear Tires Replaced
Includes mounting, tire balance & rotation .
Firestone Complete Autocare : 13818 NE 175th St, Woodinville, WA 98072 (425) 686-7370

Labor: $0.00 **Parts:** $0.00 **Job Total:** $0.00

Detail Shop

Labor: $0.00 **Parts:** $0.00 **Job Total:** $249.95

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.
I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Limited Warranty:

The standard warranty for repairs and/or service performed by 405 Motors service facility is 6 months or 6,000 miles, whichever comes first, and is limited only to the repairs we made. Any exception would have to be made in writing and signed by 405 Motors. Warranty repairs and service have to be completed and performed by 405 motors service facility and cannot exceed the original cost of repair. Our warranty is non-transferable and/or non-assingable to any other party other than the registered owner at the time of repair. Neglect and abuse, including installing any performance parts, voids warranty. Our warranty does not cover consequential damage. Our warranty does not cover towing.

Labor Total:	$589.90
Parts Total:	$285.68
Shop Supplies:	$17.51
HazMat:	$17.51
Sub Total:	$910.60
Tax Total:	$0.00
Estimate Total:	**$910.60**

SIGNATURE..... **Date**.....