

405 MOTORS

08/16/2017 11:08:20 AM

24115 SNOHOMISH WOODINVILLE RD
WOODINVILLE, WA 98072

Invoice #
2912

Phone: 425-486-4240 Fax: 425- -

405 MOTORS

SALES DEPARTMENT

6430 240TH ST SE
WOODINVILLE, WA 98072
Cell 425-949-4550

2006 Subaru B9 Tribeca Gray

License: 420422

VIN: 4S4WX82C864420422

Eng: 3L, H6 (183CI) VIN(8)

Unit #: 420422

INVOICE

Vehicle Time In: 8/16/2017 11:05:45AM

Pre-Sale Multipoint Inspection 208953km; 04/18/17

Front Brakes: 40%
Rear Brakes: 40%
Front Tires : LF 8/32 RF 8/32
Rear Tires : LR 8/32 RR 8/32

Oil Service: Engine Oil SAE Conventional Synthetic Blend w/ Filter

This vehicle has been checked for the following systems & components:

1. Fluids & Filters; Belts & Hoses; Wheels & Tires; Head & Tail Lamps
2. Charging System - Battery, Alternator, Terminals and relevant electrical wiring
3. Powertrain – Engine, Transmission, Transfer Case (if applicable), Drive Axle (if applicable)
4. Engine Cooling System – Radiator & Acc. Fan; Water Pump & Thermostat; Relevant Hoses
5. A/C system – AC Compressor; Blower Motor; AC Lines & Heating Operation
6. Suspension – Shocks & Struts; Adjustment Height Systems; Spring Assembly; Links & Bushings; CV Axles & Joints;
7. Exhaust System – Muffler, Exhaust Piping; Resonator and Exhaust Hangers
8. Drivability – Before & after performance and operation test

Please note that additional services may be required as part of the regular maintenance.

Recommendations & Notes:

Labor: \$0.00	Parts: \$0.00	Sublet: \$120.00	Job Total: \$120.00
----------------------	----------------------	-------------------------	----------------------------

Engine Oil SAE 5W30 Synthetic Blend

Lube, Oil & Filter

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
MGA46914	Air Filter	1.00	\$17.66	\$17.66
Labor: \$39.95	Parts: \$17.66	Sublet: \$0.00	Job Total: \$57.61	

Battery

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
35PRMJ	Battery	1.00	\$148.34	\$148.34
Labor: \$40.00	Parts: \$148.34	Sublet: \$0.00	Job Total: \$188.34	

RADIATOR - Remove & Replace - All Applicable Models - [Includes: R&I Front Bumper Assembly.]

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
221-3610	Radiator - Plastic Tank	1.00	\$275.47	\$275.47
Labor: \$200.00	Parts: \$275.47	Sublet: \$0.00	Job Total: \$475.47	

Coolant

Labor: \$49.95	Parts: \$0.00	Sublet: \$0.00	Job Total: \$49.95
-----------------------	----------------------	-----------------------	---------------------------



405 MOTORS

24115 SNOHOMISH WOODINVILLE RD
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

08/16/2017 11:08:20 AM

Invoice #
2912

405 MOTORS

SALES DEPARTMENT

6430 240TH ST SE
WOODINVILLE, WA 98072
Cell 425-949-4550

2006 Subaru B9 Tribeca Gray

License: 420422

VIN: 4S4WX82C864420422

Eng: 3L, H6 (183CI) VIN(8)

Unit #: 420422

INVOICE

Continued From Previous Page

Diagnosis: CEL

1. Code: P0301 CYL 1 MISFIRE - check spark plug, injectors & coil pack. All look good - no sign of water or burning - all look relatively newer.
2. Found crank position wire chewed - repair wire. Checked other wires for further rodent damage. Found minor bites - no cut-through. Secured & repaired all wires.
3. Cleaned MAF & TPS sensors and cleaned the intake runners - reset light but code present almost immediately.
4. Replaced water temp sensor since it connected directly w/ cylinder 1 - code present after install.
5. checked connector pins & inputs on the ECM and found the connectors in good condition.

SUBARU EASTSIDE DIAGNOSIS - recommend OEM spark plug from subaru - misfire travelling from #1 to #3 when swapping existing spark plugs.

Part Number	Description	Quantity	Sale	Extended
22630 AA140	Water Temp. Sensor	2.00	\$30.36	\$60.72
Labor: \$400.00				
Parts: \$60.72				
Sublet:\$0.00				
			Job Total:	\$460.72

Spark Plug

Part Number	Description	Quantity	Sale	Extended
22401AA630	Spark Plug	6.00	\$15.95	\$95.70
Check engine light resolved.				
Labor: \$80.00				
Parts: \$95.70				
Sublet:\$0.00				
			Job Total:	\$175.70

Detail Shop

Labor: \$0.00				
Parts: \$0.00				
Sublet:\$249.95				
			Job Total:	\$249.95



405 MOTORS

24115 SNOHOMISH WOODINVILLE RD
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

08/16/2017 11:08:20 AM

Invoice #
2912

405 MOTORS

SALES DEPARTMENT

6430 240TH ST SE
WOODINVILLE, WA 98072
Cell 425-949-4550

2006 Subaru B9 Tribeca Gray

License: 420422

VIN: 4S4WX82C864420422

Eng: 3L, H6 (183CI) VIN(8)

Unit #: 420422

INVOICE

Continued From Previous Page

Declined Work

05/04/2017 RADIATOR - Remove & Replace - All Applicable Models - [Includes: R&I Front Bumper Assembly.]

Estimate

\$1,513

Technician(s):

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Limited Warranty:

The standard warranty for repairs and/or service performed by 405 Motors service facility is 6 months or 6,000 miles, whichever comes first, and is limited only to the repairs we made. Any exception would have to be made in writing and signed by 405 Motors. Warranty repairs and service have to be completed and performed by 405 motors service facility and cannot exceed the original cost of repair. Our warranty is non-transferable and/or non-assignable to any other party other than the registered owner at the time of repair. Neglect and abuse, including installing any performance parts, voids warranty. Our warranty does not cover consequential damage. Our warranty does not cover towing.

Labor Total:	\$809.90
Parts Total:	\$597.89
Sublet Total:	\$369.95
Shop Supplies:	\$25.00
HazMat:	\$11.96

Sub Total:	\$1,814.70
Tax Total:	\$0.00
Grand Total:	\$1,814.70
Balance Due:	\$1,814.70



SIGNATURE.....

DATE.....

405 MOTORS
\$119.95
Coolant Flush
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

405 MOTORS
\$179.95
Trans Flush
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

405 MOTORS
\$139.95
Brake Flush
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

