

405 MOTORS

24115 SNOHOMISH WOODINVILLE RD
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

11/20/2017 7:34:01 PM

Invoice #
5192

405 MOTORS

Sales Department

6430 240th ST SE
Woodinville, WA 98072
Cell 425-949-4550

2005 Toyota Highlander Black

License: 067964

VIN: JTEEP21A050067964

Eng: 3.3L, V6 (202CI) VIN(P)

Unit #: 067964

INVOICE

Vehicle Time In: 11/20/2017 7:33:55PM

Perform Multipoint Inspection

11/18/2017-111666

Front Brakes: 100%

Rear Brakes: 100%

Front Tires : LF 5/32 RF 5/32

Rear Tires : LR 5/32 RR 5/32

Oil Service: Engine Oil SAE Conventional Synthetic Blend w/ Filter

This vehicle has been checked for the following systems & components:

1. Fluids & Filters; Belts & Hoses; Wheels & Tires; Head & Tail Lamps
2. Charging System - Battery, Alternator, Terminals and relevant electrical wiring
3. Powertrain – Engine, Transmission, Transfer Case (if applicable), Drive Axle (if applicable)
4. Engine Cooling System – Radiator & Acc. Fan; Water Pump & Thermostat; Relevant Hoses
5. A/C system – AC Compressor; Blower Motor; AC Lines & Heating Operation
6. Suspension – Shocks & Struts; Adjustment Height Systems; Spring Assembly; Links & Bushings; CV Axles & Joints;
7. Exhaust System – Muffler, Exhaust Piping; Resonator and Exhaust Hangers
8. Drivability – Before & after performance and operation test

Please note that additional services may be required as part of the regular maintenance.

Recommendations & Notes:

- tech states that timing belt looks to have been done recently

Labor: \$0.00

Parts: \$0.00

Sublet: \$120.00

Job Total: \$120.00

Engine Oil SAE 5W30 Synthetic Blend

Lube, Oil & Filter

Part Number	Description	Quantity	Sale	Extended
12A	Window Wiper Blade-Rear - 900 Rear Blade	1.00	\$11.99	\$11.99

Labor: \$39.95

Parts: \$11.99

Sublet: \$0.00

Job Total: \$51.94

Window Motor & Regulator; Front Right

Part Number	Description	Quantity	Sale	Extended
749-610	Window Regulator	1.00	\$78.41	\$78.41
47-10008	Power Window Motor	1.00	\$122.89	\$122.89

Labor: \$120.00

Parts: \$201.30

Sublet: \$0.00

Job Total: \$321.30

Front Rear Tires Replaced

Includes mounting, tire balance & rotation.

Firestone Complete Autocare: 13818 NE 175th St, Woodinville, WA 98072 (425) 686-7370

Check charging system

Drivability and performance checked

Engine Checked

Transmission Inspection

Brake Inspection



405 MOTORS

24115 SNOHOMISH WOODINVILLE RD
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

11/20/2017 7:34:01 PM

Invoice #
5192

405 MOTORS

Sales Department

6430 240th ST SE
Woodinville, WA 98072
Cell 425-949-4550

2005 Toyota Highlander Black

License: 067964

VIN: JTEEP21A050067964

Eng: 3.3L, V6 (202CI) VIN(P)

Unit #: 067964

INVOICE

Continued From Previous Page

Drivetrain Checked

Cooling and Heating Check

Check suspension components

Inspect Differential

Inspect Power Steering System

Exhaust System Checked

Lights Checked

Wheels Checked

Fluid Check

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
--------------------	--------------------	-----------------	-------------	-----------------

Detail Shop

Labor: \$0.00

Parts: \$0.00

Sublet: \$249.95

Job Total: \$249.95



405 MOTORS

24115 SNOHOMISH WOODINVILLE RD
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

11/20/2017 7:34:01 PM

Invoice #
5192

405 MOTORS

Sales Department

6430 240th ST SE
Woodinville, WA 98072
Cell 425-949-4550

2005 Toyota Highlander Black

License: 067964

VIN: JTEEP21A050067964

Eng: 3.3L, V6 (202CI) VIN(P)

Unit #: 067964

INVOICE

Continued From Previous Page

Technician(s):

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Limited Warranty:

The standard warranty for repairs and/or service performed by 405 Motors service facility is 6 months or 6,000 miles, whichever comes first, and is limited only to the repairs we made. Any exception would have to be made in writing and signed by 405 Motors. Warranty repairs and service have to be completed and performed by 405 motors service facility and cannot exceed the original cost of repair. Our warranty is non-transferable and/or non-assignable to any other party other than the registered owner at the time of repair. Neglect and abuse, including installing any performance parts, voids warranty. Our warranty does not cover consequential damage. Our warranty does not cover towing.

Labor Total:	\$159.95
Parts Total:	\$213.29
Sublet Total:	\$369.95
Shop Supplies:	\$15.90
HazMat:	\$4.27

Sub Total:	\$763.36
Tax Total:	\$0.00
Grand Total:	\$763.36
Balance Due:	\$763.36



SIGNATURE.....

DATE.....

405 MOTORS
\$119.95
Coolant Flush
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

405 MOTORS
\$179.95
Trans Flush
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

405 MOTORS
\$139.95
Brake Flush
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

