

405 MOTORS

24115 SNOHOMISH WOODINVILLE RD
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

08/09/2017 2:04:05 PM

Invoice #
3307

405 MOTORS

SALES DEPARTMENT

6430 240TH ST SE
WOODINVILLE, WA 98072
Cell 425-949-4550



2004 Acura TL Gold

Odometer In: 77247

License: 003354

VIN: 19UUA662X4A003354

Eng: 3.2L, V6 (196CI) VIN(UA6)

Unit #: 003354

INVOICE

Vehicle Time In: 7/8/2017 10:24:18AM

Vehicle Time Out: 7/8/2017 10:25:13AM

Perform Multipoint Inspection

Brakes: FR 90% RR 75%

Tires: LF 10/32 LR 10/32 RF 10/32 RR 10/32

Oil Service: Engine Oil SAE 5W30 Synthetic Blend w/ Filter

This vehicle has been checked for the following components:

1. Fluids, Belts, Wipers, Bulbs, Tires, Wheels, Alignment, Basic Power Options.
2. Charging System - Battery, Alternator, Terminals and relevant electrical wiring.
3. Engine - Idle, Leaks, Hoses, Valves, Clamps and overall visual condition.
4. Transmission, Clutch, CV joints & axles, Transfer case, Drive axle, Drive shaft and U-joints.
5. Suspension -Struts & Shocks, Bushings, Links and spring assembly.
6. Water pump, Radiator & acc. Fan, Thermostat and applicable cooling system hoses & Tubes.
7. AC Compressor, AC Clutch, Blower motor, AC Lines and Heating.
8. Exhaust System – Muffler, Exhaust & Y-Pipe, Resonator and applicable clamps & holders.
9. Drivability – pre-inspection test drive and post-service drivability test drive.

Please note that additional services may be required as part of the regular maintenance.

Notes & Recommended items:

Labor: \$0.00	Parts: \$0.00	Sublet: \$120.00	Job Total: \$120.00
----------------------	----------------------	-------------------------	----------------------------

Engine Oil SAE 5W30 Synthetic Blend

Lube, Oil & Filter
Filter 15400-PLC-004

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
74149-SEP-A01	Hood Strut-Right	1.00	\$33.66	\$33.66
74149-SEP-A01	Hood Strut-Right	1.00	\$33.66	\$33.66

Labor: \$39.95	Parts: \$67.32	Sublet: \$0.00	Job Total: \$107.27
-----------------------	-----------------------	-----------------------	----------------------------

Front brake rotor

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
45251-SEP-A51	Brake Disc-Front	2.00	\$46.37	\$92.74

Labor: \$80.00	Parts: \$92.74	Sublet: \$0.00	Job Total: \$172.74
-----------------------	-----------------------	-----------------------	----------------------------

Front Rear Tires Replaced

Includes mounting, tire balance & rotation.

Firestone Complete Autocare: 13818 NE 175th St, Woodinville, WA 98072 (425) 686-7370

Labor: \$0.00	Parts: \$0.00	Sublet: \$0.00	Job Total: \$0.00
----------------------	----------------------	-----------------------	--------------------------

Detail Shop

Labor: \$0.00	Parts: \$0.00	Sublet: \$249.95	Job Total: \$249.95
----------------------	----------------------	-------------------------	----------------------------



405 MOTORS

24115 SNOHOMISH WOODINVILLE RD
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

08/09/2017 2:04:05 PM

Invoice #
3307

405 MOTORS

SALES DEPARTMENT

6430 240TH ST SE
WOODINVILLE, WA 98072
Cell 425-949-4550



2004 Acura TL Gold

Odometer In: 77247

License: 003354

Unit #: 003354

VIN: 19UUA662X4A003354

Eng: 3.2L, V6 (196CI) VIN(UA6)

INVOICE

Continued From Previous Page

Technician(s):

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Limited Warranty:

The standard warranty for repairs and/or service performed by 405 Motors service facility is 6 months or 6,000 miles, whichever comes first, and is limited only to the repairs we made. Any exception would have to be made in writing and signed by 405 Motors. Warranty repairs and service have to be completed and performed by 405 motors service facility and cannot exceed the original cost of repair. Our warranty is non-transferable and/or non-assignable to any other party other than the registered owner at the time of repair. Neglect and abuse, including installing any performance parts, voids warranty. Our warranty does not cover consequential damage. Our warranty does not cover towing.

Labor Total:	\$119.95
Parts Total:	\$160.06
Sublet Total:	\$369.95
Shop Supplies:	\$13.00
HazMat:	\$13.00

Sub Total:	\$675.96
Tax Total:	\$0.00
Grand Total:	\$675.96
Balance Due:	\$0.00



SIGNATURE.....

DATE.....

Payment(s)

7/8/2017 10:25:11AM

\$675.96

Internal Pay

405 MOTORS

\$119.95

Coolant Flush
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

405 MOTORS

\$179.95

Trans Flush
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

405 MOTORS

\$139.95

Brake Flush
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

