

# 405 MOTORS

24115 SNOHOMISH WOODINVILLE RD  
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

08/05/2017 5:04:22 PM

Invoice #  
**3104**

## 405 MOTORS

### SALES DEPARTMENT

6430 240TH ST SE  
WOODINVILLE, WA 98072  
Cell 425-949-4550



### 2003 Honda Pilot LX Silver

Odometer In: 149563  
License: 604776  
VIN: 2HKYF18163H604776  
Eng: 3.5L, V6 (212CI) VIN(YF1)

Unit #: 604776

## INVOICE

Vehicle Time In: 6/10/2017 1:12:44PM

Vehicle Time Out: 6/10/2017 1:12:47PM

### Perform Multipoint Inspection

This vehicle has been checked for the following components:

Front brakes at 80% and Rear brakes at 75%  
Front Tires at 8/32nd and Rear Tires at 8/32nd

Essentials – Fluids, Belts, Wipers, Bulbs, Tires, Wheels, Alignment, Basic Power Options.  
Charging System - Battery, Alternator, Terminals and relevant electrical wiring.  
Engine – Idle, Leaks, Hoses, Valves, Clamps and overall visual condition.  
Powertrain – Transmission, Clutch, CV joints & axles, Transfer case, Drive axle, Drive shaft and U-joints.  
Suspension – Struts & Shocks, Bushings, Links and spring assembly.  
Cooling System – Water pump, Radiator & acc. Fan, Thermostat and applicable hoses & Tubes.  
AC & EVAC – Compressor, AC Clutch, Blower motor, AC Lines and Heating.  
Exhaust System – Muffler, Exhaust & Y-Pipe, Resonator and applicable clamps & holders.  
Drivability – pre-inspection test drive and post-service drivability test drive.

Please note that additional services may be required as part of the regular maintenance.

Recommended items not performed by 405motors:

**Labor:** \$0.00                      **Parts:** \$0.00                      **Sublet:** \$100.00                      **Job Total:** \$100.00

### Knock Sensor

| Part Number   | Description                  | Quantity | Sale     | Extended |
|---------------|------------------------------|----------|----------|----------|
| 30530-P8F-A01 | Knock Sensor                 | 1.00     | \$61.41  | \$61.41  |
| 30531-P8F-A00 | Knock Sensor Harness         | 1.00     | \$8.20   | \$8.20   |
| 17055-P8E-A01 | Intake Manifold Gasket-Left  | 1.00     | \$23.56  | \$23.56  |
| 17065-P8E-A01 | Intake Manifold Gasket-Right | 1.00     | \$23.56  | \$23.56  |
| 17105-P8E-A01 | Intake Plenum Gasket-Lower   | 2.00     | \$27.37  | \$54.74  |
| 17146-P8E-A21 | Intake Plenum Gasket-Upper   | 1.00     | \$28.42  | \$28.42  |
| 06164-P8E-A00 | Fuel Injector                | 1.00     | \$131.57 | \$131.57 |

**Labor:** \$500.00                      **Parts:** \$331.46                      **Sublet:** \$0.00                      **Job Total:** \$831.46

### Engine Oil SAE 5W30 Synthetic Blend

Lube, Oil & Filter

**Labor:** \$39.95                      **Parts:** \$0.00                      **Sublet:** \$0.00                      **Job Total:** \$39.95

### Transmission Drain & Fill

**Labor:** \$59.95                      **Parts:** \$0.00                      **Sublet:** \$0.00                      **Job Total:** \$59.95

### Front differential Service

Remove cover. Remove old gasket material, drain old fluid, inspect internals and reassemble with new gasket. Install new fluid to proper levels. Road test vehicle for proper operation.

**Labor:** \$89.95                      **Parts:** \$0.00                      **Sublet:** \$0.00                      **Job Total:** \$89.95



# 405 MOTORS

24115 SNOHOMISH WOODINVILLE RD  
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

08/05/2017 5:04:22 PM

Invoice #  
**3104**

## 405 MOTORS

### SALES DEPARTMENT

6430 240TH ST SE  
WOODINVILLE, WA 98072  
Cell 425-949-4550



### 2003 Honda Pilot LX Silver

Odometer In: 149563  
License: 604776  
VIN: 2HKYF18163H604776  
Eng: 3.5L, V6 (212CI) VIN(YF1)  
Unit #: 604776

## INVOICE

*Continued From Previous Page*

### Rear differential Service

Remove cover. Remove old gasket material, drain old fluid. Inspect internals and reassemble with new gasket. Install new fluid to proper level. Road test vehicle for proper operation.

**Labor:** \$89.95      **Parts:** \$0.00      **Sublet:**\$0.00      **Job Total:** \$89.95

### Air Conditioning Evacuate & Recharge

| Part Number            | Description               | Quantity              | Sale                       | Extended |
|------------------------|---------------------------|-----------------------|----------------------------|----------|
| 0000R134a              | AC Refrigerant R134a 1lbs | 3.00                  | \$25.00                    | \$75.00  |
| <b>Labor:</b> \$100.00 | <b>Parts:</b> \$75.00     | <b>Sublet:</b> \$0.00 | <b>Job Total:</b> \$175.00 |          |

### Check charging system

**Labor:** \$0.00      **Parts:** \$0.00      **Sublet:**\$0.00      **Job Total:** \$0.00

### Drivability and performance checked

**Labor:** \$0.00      **Parts:** \$0.00      **Sublet:**\$0.00      **Job Total:** \$0.00

### Engine Checked

**Labor:** \$0.00      **Parts:** \$0.00      **Sublet:**\$0.00      **Job Total:** \$0.00

### Transmission Inspection

**Labor:** \$0.00      **Parts:** \$0.00      **Sublet:**\$0.00      **Job Total:** \$0.00

### Brake Inspection

**Labor:** \$0.00      **Parts:** \$0.00      **Sublet:**\$0.00      **Job Total:** \$0.00

### Drivetrain Checked

**Labor:** \$0.00      **Parts:** \$0.00      **Sublet:**\$0.00      **Job Total:** \$0.00

### Cooling and Heating Check

**Labor:** \$0.00      **Parts:** \$0.00      **Sublet:**\$0.00      **Job Total:** \$0.00

### Check suspension components

**Labor:** \$0.00      **Parts:** \$0.00      **Sublet:**\$0.00      **Job Total:** \$0.00

### Inspect Differential

**Labor:** \$0.00      **Parts:** \$0.00      **Sublet:**\$0.00      **Job Total:** \$0.00

### Inspect Power Steering System

**Labor:** \$0.00      **Parts:** \$0.00      **Sublet:**\$0.00      **Job Total:** \$0.00

### Exhaust System Checked

**Labor:** \$0.00      **Parts:** \$0.00      **Sublet:**\$0.00      **Job Total:** \$0.00



# 405 MOTORS

24115 SNOHOMISH WOODINVILLE RD  
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

08/05/2017 5:04:22 PM

Invoice #  
**3104**

## 405 MOTORS

### SALES DEPARTMENT

6430 240TH ST SE  
WOODINVILLE, WA 98072  
Cell 425-949-4550



### 2003 Honda Pilot LX Silver

Odometer In: 149563

License: 604776

VIN: 2HKYF18163H604776

Eng: 3.5L, V6 (212CI) VIN(YF1)

Unit #: 604776

## INVOICE

*Continued From Previous Page*

### Lights Checked

**Labor:** \$0.00                      **Parts:** \$0.00                      **Sublet:**\$0.00                      **Job Total:** \$0.00

### Wheels Checked

**Labor:** \$0.00                      **Parts:** \$0.00                      **Sublet:**\$0.00                      **Job Total:** \$0.00

### Fluid Check

| <u>Part Number</u>   | <u>Description</u> |                      | <u>Quantity</u> | <u>Sale</u>           | <u>Extended</u>          |
|----------------------|--------------------|----------------------|-----------------|-----------------------|--------------------------|
| <b>Labor:</b> \$0.00 |                    | <b>Parts:</b> \$0.00 |                 | <b>Sublet:</b> \$0.00 | <b>Job Total:</b> \$0.00 |

### Detail Shop

**Labor:** \$0.00                      **Parts:** \$0.00                      **Sublet:**\$250.00                      **Job Total:** \$250.00



# 405 MOTORS

24115 SNOHOMISH WOODINVILLE RD  
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

08/05/2017 5:04:22 PM

Invoice #  
**3104**

## 405 MOTORS

### SALES DEPARTMENT

6430 240TH ST SE  
WOODINVILLE, WA 98072  
Cell 425-949-4550



### 2003 Honda Pilot LX Silver

Odometer In: 149563  
License: 604776  
Unit #: 604776  
VIN: 2HKYF18163H604776  
Eng: 3.5L, V6 (212CI) VIN(YF1)

## INVOICE

Continued From Previous Page

Technician(s):

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Limited Warranty:

The standard warranty for repairs and/or service performed by 405 Motors service facility is 6 months or 6,000 miles, whichever comes first, and is limited only to the repairs we made. Any exception would have to be made in writing and signed by 405 Motors. Warranty repairs and service have to be completed and performed by 405 motors service facility and cannot exceed the original cost of repair. Our warranty is non-transferable and/or non-assignable to any other party other than the registered owner at the time of repair. Neglect and abuse, including installing any performance parts, voids warranty. Our warranty does not cover consequential damage. Our warranty does not cover towing.

|                     |               |
|---------------------|---------------|
| Labor Total:        | \$879.80      |
| Parts Total:        | \$406.46      |
| Sublet Total:       | \$350.00      |
| Shop Supplies:      | \$8.13        |
| HazMat:             | \$24.60       |
| -----               |               |
| Sub Total:          | \$1,668.99    |
| Tax Total:          | \$0.00        |
| Grand Total:        | \$1,668.99    |
| <b>Balance Due:</b> | <b>\$0.00</b> |



SIGNATURE.....

DATE.....

Payment(s)

6/10/2017 1:12:46PM \$1,668.99

Internal Pay

405 MOTORS  
**\$119.95**  
Coolant Flush  
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

405 MOTORS  
**\$179.95**  
Trans Flush  
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

405 MOTORS  
**\$139.95**  
Brake Flush  
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

