

# 405 MOTORS

24115 SNOHOMISH WOODINVILLE RD  
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

09/02/2017 2:32:33 PM

Invoice #  
**3512**

## 405 MOTORS

### SALES DEPARTMENT

6430 240TH ST SE  
WOODINVILLE, WA 98072  
Cell 425-949-4550

### 2007 Honda Odyssey EX Gold

Odometer In: 92441  
License: 079637 VIN: 5FNRL38657B079637  
Eng: 3.5L, V6 (212CI) VIN(RL3)  
Unit #: 079637

## INVOICE

Vehicle Time In: 9/2/2017 2:31:55PM

### Pre-Sale Multipoint Inspection

Front Brakes: 65%  
Rear Brakes: 60%  
Front Tires : LF 7/32 RF 7/32  
Rear Tires : LR 7/32 RR 7/32

Oil Service: Engine Oil SAE Conventional Synthetic Blend w/ Filter

This vehicle has been checked for the following systems & components:

1. Fluids & Filters; Belts & Hoses; Wheels & Tires; Head & Tail Lamps
2. Charging System - Battery, Alternator, Terminals and relevant electrical wiring
3. Powertrain – Engine, Transmission, Transfer Case (if applicable), Drive Axle (if applicable)
4. Engine Cooling System – Radiator & Acc. Fan; Water Pump & Thermostat; Relevant Hoses
5. A/C system – AC Compressor; Blower Motor; AC Lines & Heating Operation
6. Suspension – Shocks & Struts; Adjustment Height Systems; Spring Assembly; Links & Bushings; CV Axles & Joints;
7. Exhaust System – Muffler, Exhaust Piping; Resonator and Exhaust Hangers
8. Drivability – Before & after performance and operation test

Please note that additional services may be required as part of the regular maintenance.

Recommendations & Notes:

<b>Labor:</b> \$0.00	<b>Parts:</b> \$0.00	<b>Sublet:</b> \$120.00	<b>Job Total:</b> \$120.00
----------------------	----------------------	-------------------------	----------------------------

### Engine Oil SAE 5W30 Synthetic Blend

Lube, Oil & Filter

<b>Labor:</b> \$39.95	<b>Parts:</b> \$0.00	<b>Sublet:</b> \$0.00	<b>Job Total:</b> \$39.95
-----------------------	----------------------	-----------------------	---------------------------

### Shock Absorber-Rear

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
349105	Shock Absorber-Rear	2.00	\$75.12	\$150.24
<b>Labor:</b> \$96.00	<b>Parts:</b> \$150.24	<b>Sublet:</b> \$0.00	<b>Job Total:</b> \$246.24	

### Detail Shop

<b>Labor:</b> \$0.00	<b>Parts:</b> \$0.00	<b>Sublet:</b> \$249.95	<b>Job Total:</b> \$249.95
----------------------	----------------------	-------------------------	----------------------------



# 405 MOTORS

24115 SNOHOMISH WOODINVILLE RD  
WOODINVILLE, WA 98072

Phone: 425-486-4240 Fax: 425- -

09/02/2017 2:32:33 PM

Invoice #  
**3512**

## 405 MOTORS

### SALES DEPARTMENT

6430 240TH ST SE  
WOODINVILLE, WA 98072  
Cell 425-949-4550

### 2007 Honda Odyssey EX Gold

Odometer In: 92441  
License: 079637  
VIN: 5FNRL38657B079637  
Eng: 3.5L, V6 (212CI) VIN(RL3)  
Unit #: 079637

## INVOICE

*Continued From Previous Page*

### Declined Work

09/02/2017 DOOR WINDOW MOTOR

### Estimate

\$324

Technician(s):

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Limited Warranty:

The standard warranty for repairs and/or service performed by 405 Motors service facility is 6 months or 6,000 miles, whichever comes first, and is limited only to the repairs we made. Any exception would have to be made in writing and signed by 405 Motors. Warranty repairs and service have to be completed and performed by 405 motors service facility and cannot exceed the original cost of repair. Our warranty is non-transferable and/or non-assignable to any other party other than the registered owner at the time of repair. Neglect and abuse, including installing any performance parts, voids warranty. Our warranty does not cover consequential damage. Our warranty does not cover towing.

Labor Total:	\$135.95
Parts Total:	\$150.24
Sublet Total:	\$369.95
Shop Supplies:	\$15.18
HazMat:	\$3.00
-----	
Sub Total:	\$674.32
Tax Total:	\$0.00
Grand Total:	\$674.32
<b>Balance Due:</b>	<b>\$674.32</b>



SIGNATURE.....

DATE.....

405 MOTORS  
**\$119.95**  
Coolant Flush  
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

405 MOTORS  
**\$179.95**  
Trans Flush  
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

405 MOTORS  
**\$139.95**  
Brake Flush  
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

