

# 405 MOTORS SERVICE CENTER

24115 SNOHOMISH WOODINVILLE RD  
WOODINVILLE, WA 98072  
Phone: 425-949-4550 Fax: 425-329-3111

01/06/2018 3:05:25 PM

Invoice #  
**5404**

## 405 MOTORS

### Sales Department

6430 240th ST SE  
Woodinville, WA 98072  
Cell 425-949-4550

### 2006 BMW X5 44i Silver

License: V29032

VIN: 5UXFB53566LV29032

Eng: 4.4L, V8 (268CI) VIN(3)

Unit #: V29032

## INVOICE

Vehicle Time In: 1/6/2018 3:05:18PM

### Perform Multipoint Inspection 12/15/2017-98207

Front Brakes: 50%  
Rear Brakes: 90%  
Front Tires : LF 6/32 RF 6/32  
Rear Tires : LR 6/32 RR 6/32

Oil Service: Engine Oil SAE Full Synthetic w/ Filter

This vehicle has been checked for the following systems & components:

1. Fluids & Filters; Belts & Hoses; Wheels & Tires; Head & Tail Lamps
2. Charging System - Battery, Alternator, Terminals and relevant electrical wiring
3. Powertrain – Engine, Transmission, Transfer Case (if applicable), Drive Axle (if applicable)
4. Engine Cooling System – Radiator & Acc. Fan; Water Pump & Thermostat; Relevant Hoses
5. A/C system – AC Compressor; Blower Motor; AC Lines & Heating Operation
6. Suspension – Shocks & Struts; Adjustment Height Systems; Spring Assembly; Links & Bushings; CV Axles & Joints;
7. Exhaust System – Muffler, Exhaust Piping; Resonator and Exhaust Hangers
8. Drivability – Before & after performance and operation test

Please note that additional services may be required as part of the regular maintenance.

#### Recommendations & Notes:

**Labor:** \$0.00      **Parts:** \$0.00      **Sublet:** \$120.00      **Job Total:** \$120.00

### Engine Oil Full Synthetic - 5W40 SAE

Lube, Oil & Filter

07 11 9 963 308	Oil Drain Plug Gasket	1.00	\$1.56	\$1.56
<b>Labor:</b> \$0.00	<b>Parts:</b> \$1.56	<b>Sublet:</b> \$109.95	<b>Job Total:</b> \$111.51	

### SPARK PLUGS - Remove & Replace - V8

Part Number	Description	Quantity	Sale	Extended
0 242 236 562	Spark Plug FGR 7 DQP+	8.00	\$12.27	\$98.16
12 13 8 657 273	Direct Ignition Coil Eldor	8.00	\$58.31	\$466.48
<b>Labor:</b> \$128.00	<b>Parts:</b> \$564.64	<b>Sublet:</b> \$0.00	<b>Job Total:</b> \$692.64	

### POWER STEERING HOSE - Remove & Replace - V8 Each,Return or Suction - [Includes: Bleed System.]

Part Number	Description	Quantity	Sale	Extended
32 41 6 763 979	P/S Return Hose-Rack To Cooler	1.00	\$128.72	\$128.72
RCS 16 X 22	Seal Ring - Copper	2.00	\$2.64	\$5.28
<b>Labor:</b> \$56.00	<b>Parts:</b> \$134.00	<b>Sublet:</b> \$0.00	<b>Job Total:</b> \$190.00	

### Front brake service

Part Number	Description	Quantity	Sale	Extended
34 11 6 794 300	Brake Disc-Front - Vented	2.00	\$94.05	\$188.10
34 11 6 761 252	Brake Pad Set-Front - With Shims	1.00	\$87.20	\$87.20
34 35 1 165 579	Brake Pad Sensor-Front	1.00	\$15.86	\$15.86



# 405 MOTORS SERVICE CENTER

24115 SNOHOMISH WOODINVILLE RD  
WOODINVILLE, WA 98072  
Phone: 425-949-4550 Fax: 425-329-3111

01/06/2018 3:05:25 PM

Invoice #  
**5404**

## 405 MOTORS

### Sales Department

6430 240th ST SE  
Woodinville, WA 98072  
Cell 425-949-4550

### 2006 BMW X5 44i Silver

License: V29032

VIN: 5UXFB53566LV29032

Eng: 4.4L, V8 (268CI) VIN(3)

Unit #: V29032

## INVOICE

*Continued From Previous Page*

BHH	Disc Brake Kit		1.00	\$15.58	\$15.58
<b>Labor:</b> \$96.00		<b>Parts:</b> \$306.74			<b>Sublet:</b> \$0.00
					<b>Job Total:</b> \$402.74

### Drag Link Control Arms; Front Left & Right

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>	
31 12 6 760 276	Control Arm-Front Right Lower Rearward	1.00	\$96.56	\$96.56	
31 12 6 760 275	Control Arm-Front Left Lower Rearward	1.00	\$96.56	\$96.56	
<b>Labor:</b> \$240.00		<b>Parts:</b> \$193.12		<b>Sublet:</b> \$0.00	
					<b>Job Total:</b> \$433.12

### Wheel Alignment

<b>Labor:</b> \$0.00	<b>Parts:</b> \$0.00	<b>Sublet:</b> \$79.95	<b>Job Total:</b> \$79.95
----------------------	----------------------	------------------------	---------------------------

### Check charging system

### Drivability and performance checked

### Engine Checked

### Transmission Inspection

### Brake Inspection

### Drivetrain Checked

### Cooling and Heating Check

### Check suspension components

### Inspect Differential

### Inspect Power Steering System

### Exhaust System Checked

### Lights Checked

### Wheels Checked

### Fluid Check

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
--------------------	--------------------	-----------------	-------------	-----------------

### Detail Shop

<b>Labor:</b> \$0.00	<b>Parts:</b> \$0.00	<b>Sublet:</b> \$249.95	<b>Job Total:</b> \$249.95
----------------------	----------------------	-------------------------	----------------------------



# 405 MOTORS SERVICE CENTER

24115 SNOHOMISH WOODINVILLE RD  
WOODINVILLE, WA 98072

Phone: 425-949-4550 Fax: 425-329-3111

01/06/2018 3:05:25 PM

Invoice #  
**5404**

## 405 MOTORS

### Sales Department

6430 240th ST SE  
Woodinville, WA 98072  
Cell 425-949-4550

### 2006 BMW X5 44i Silver

License: V29032

VIN: 5UXFB53566LV29032

Eng: 4.4L, V8 (268CI) VIN(3)

Unit #: V29032

## INVOICE

*Continued From Previous Page*

Technician(s):

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Limited Warranty:

The standard warranty for repairs and/or service performed by 405 Motors service facility is 6 months or 6,000 miles, whichever comes first, and is limited only to the repairs we made. Any exception would have to be made in writing and signed by 405 Motors. Warranty repairs and service have to be completed and performed by 405 motors service facility and cannot exceed the original cost of repair. Our warranty is non-transferable and/or non-assignable to any other party other than the registered owner at the time of repair. Neglect and abuse, including installing any performance parts, voids warranty. Our warranty does not cover consequential damage. Our warranty does not cover towing.

Labor Total:	\$520.00
Parts Total:	\$1,200.06
Sublet Total:	\$559.85
Shop Supplies:	\$25.00
HazMat:	\$24.00
-----	
Sub Total:	\$2,328.91
Tax Total:	\$0.00
Grand Total:	\$2,328.91
<b>Balance Due:</b>	<b>\$2,328.91</b>



**SIGNATURE**.....

**DATE**.....

405 MOTORS SERVICE CENTER

**\$119.95**

Coolant Flush  
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

405 MOTORS SERVICE CENTER

**\$179.95**

Trans Flush  
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

405 MOTORS SERVICE CENTER

**\$139.95**

Brake Flush  
(On Most Vehicles)

Coupon cannot be used with any other coupon or discount. Limit one coupon per transaction.

